

PDO – TDS SHEARED BOLT HEAD

EVENT DESCRIPTION (WHAT?):

During TDS greasing a bolt with a sheared head was found on the travelling block becket pin. The bolt head was hanging by the lock wire. The sheared was removed and replaced by Motorman

CAUSES (WHY?):

- Fatigue from movement and vibration during operations.
- Wear and tear

LESSON LEARNED:

- Keep focused on perform regular PDO hunt
- Maintain daily TDS DROPS inspection during Drilling operations



DETAILS:

Report ID: PDO – TDS sheared bolt head

Location: Offshore

Area: Drilling

Type of work: Operations

Type of lesson: Dropped Object

Date of incident: 2018-05-05



