

## PDO - UNI STRUT CLAMP ON EDGE OF MODULE

### EVENT DESCRIPTION (WHAT?):

While cleaning up on pipe deck it was observed that a unistrut clamp was located near the edge of the module with the potential to drop 20 ft. Area below is a walk way which the cementer would use.

Item weighed 513 grammes

Drop Height = 20 ft

Drops Calculator equates to slight injury

### CAUSES (WHY?):

Poor house keeping

### LESSON LEARNED:

Regular cleaning and drops sweeps to be conducted



Alternative view

### DETAILS:

**Report ID:** 1117599 (Archer Synergi)

**Location:** Offshore

**Area:** Drilling

**Type of work:** Drilling

**Type of lesson:** Dropped Object

**Date of incident:** 2018-05-19



Item in situ (circled)