

PDO - PART OF SCAFFOLDING POLE FOUND ON WALKWAY

EVENT DESCRIPTION (WHAT?):

During a PDO check a part of a scaffolding pole was found lying on a walkway above the BOP deck in the structure on derrick, west side . The object was removed immediately.

Weight of the object: 1.1 kg, approx. 30 cm long.

Potential drop height: 5 m.

Drop area was not barred off.

DROPS calculator: 54 J – Minor

CAUSES (WHY?):

Left item: A scaffolding was taken down a couple of days before the observation and removal of the object. The object has most likely been forgotten when the area was cleared.

LESSON LEARNED:

Inform the 3rd party contractor about the finding and the importance of removing all loose objects after completing work



DETAILS:

Report ID: 1555877 (Equinor Synergi)

Location: Offshore

Area: Drilling

Type of work: Maintenance / Modification

Type of lesson: Dropped Object

Date of incident: 2018-09-26