

DROPPED OBJECT ON RIG FLOOR

EVENT DESCRIPTION (WHAT?):

A soft protector on rig floor beam fell down and landed inside red zone. No personnel inside red zone.

Weight of protector 2.2 kg. height 5.5 m x 9.81 = 119 Joule. The protector is made of soft material. The protector is placed on the beam to protect hoses for TD when moving TD up and down. The protector was installed next to the protector on the picture.

CAUSES (WHY?):

Protector was not included in the DROPS checklist, so the potential for it falling down was not identified.

LESSON LEARNED:

Update DROPS checklists to include this and similar equipment mounted in derrick.



DETAILS:

Report ID: 269776

Location: Offshore

Area: Well Operations

Type of work: Drilling

Type of lesson: Dropped Objects

Date of incident: 2018-11-14

Installations: EkoX

ADDITIONAL TEXT:

The protector on the picture is taken down as a precautionary measure.



