

PDO - BOLTS WITH NUTS LEFT ON TOP OF SCAFFOLD

EVENT DESCRIPTION (WHAT?):

Three bolts with nuts found on top of scaffold erected on BOP deck.

Potential drop height 6 meters.

Weight 100 g.

DROPs Calculator: 5.88 J – Slight.

CAUSES (WHY?):

Poor housekeeping

LESSON LEARNED:

PDO's removed and 3rd party contractors working in area informed of finding and requirement to improve housekeeping and safety awareness.



DETAILS:

Report ID: 1118974 (Archer Synergi)

Location: Offshore

Area: Drilling

Type of work: Maintenance / Modification

Type of lesson: Dropped Object

Date of incident: 2018-09-03